



---

## Revision Transmittal Sheet

This sheet transmits Revision 2 of Alert Service Bulletin ASB-328J-25-019 titled:  
Equipment/Furnishings - Cockpit Seats - Jammed AMSAFE Restraint System.

---

This is a complete revision. This has been reprinted in its entirety. All previous editions must be destroyed.

---

### Reason for Revision:

On May, 24<sup>th</sup> 2017 EASA issued a revision of SIB 2016-16 following new in-service events reported on seat belt buckles outside the initial batch, forcing to extend the range of impacted seat belt buckles.

Page 1: Title corrected; updated section 'Reason'

Page 2: updated section 'References'

NOTE: The changes are marked with revision bars at the outside margin.

---

This Revision Transmittal Sheet is part of ASB-328J-25-019 Revision 2 .

---

Model:   Dornier 328-300  

No.:   ASB-328J-25-019  

Date of Issue:   May 24, 2017  

Page   1   of   1



## ASB-328J-25-019

### Title: **Equipment/Furnishings - Cockpit Seats - Jammed AMSAFE Restraint System**

#### 1 PLANNING INFORMATION

##### Effectivity

Dornier 328-300  
Type Certificate Data Sheet EASA.A.096  
Serial No.: All

##### Reason

EASA Safety Information Bulletin SIB 2016-16: AMSAFE Restraint Systems – Jammed Cockpit Seat Belt Buckles

##### Description

Reports were received by EASA of occurrences where pilots were unable to release their seat belts buckles. Affected AMSAFE Rotary Buckles are installed on IPECO pilot and co-pilot seat belt restraint systems P/N 1180002-( )-( ) as installed on Dornier 328-300 aircraft.

##### Approval

The technical content of this Alert Service Bulletin is approved under the authority of EASA approved design organization 328 Design GmbH (EASA.21J.438).



© 328 Support Services GmbH 2006-2017. All Rights reserved.

This document is property of 328 Support Services GmbH and is supplied on the condition that it is treated as confidential. No use or reproduction may be made thereof other than that expressly authorized. The information provided by this ASB has been prepared for a specific Serial Number(s) aircraft, component, component part number or specific problem on the basis of the information supplied to 328 Support Services GmbH. The information provided by 328 Support Services GmbH is not to be used for any other specific serial Number(s) aircraft, component, component part number or any other purpose than for that which it was supplied without the written approval of 328 Support Services GmbH. Any information contained in this ASB are Technical Documents and Data as defined in the Technical Data Agreement which 328 Support Services GmbH has separately concluded with the Customer. The Technical Data Agreement, especially the confidentiality obligations contained therein applies to any information provided by 328 Support Services GmbH in the course of the fulfilment of the ASB.

328 Support Services GmbH is the TC-Holder of Dornier 328-100 and 328-300 and authorised to provide necessary approved data. Any Dornier 328 approved data will be established and verified by 328 Design GmbH as authorised and responsible Dornier 328 Design Organisation per EASA approval EASA 21J.438. For details in this matter please contact 328 Support Services GmbH or EASA.

It is the operator's responsibility to comply with the relevant aviation regulations of the country in which the aircraft is registered.

**Compliance**

Highly recommended

**Manpower**

As required

**Material**

Refer to AMSAFE ASB 1150004-25-A01

**Special Tools**

Refer to AMSAFE ASB 1150004-25-A01

**Weight and Balance**

Not affected

**Electrical Load Data**

Not affected

**References**

EASA Safety Information Bulletin SIB 2016-16  
or later revisions of the document approved by EASA.

AMSAFE ASB 1150004-25-A01

IPECO SB 063-25-11

Or later revisions of the above listed documents

**Other Publications Affected**

Not affected

**Reporting**

Compliance with this Alert Service Bulletin must be reported to 328 Support Services GmbH  
Global Support Centre with the Compliance Report for Configuration Control



## 2. ACCOMPLISHMENT INSTRUCTIONS

- 1.) Do the following Service Bulletin:
  - a) AMSAFE ASB 1150004-25-A01.



**Dornier 328  
Compliance Report**

**328 Support Services GmbH**  
 Customer Support • Global Support Centre  
 P. O. Box 1252 Phone: +49 8153 88111 6666  
 D-82231 Wessling Telefax: +49 8153 88111 6565  
 Germany E-Mail: gsc.op@328.eu



**Please complete this compliance form for each aircraft only when it is applicable, and mail, e-mail, or fax to:**

328 Support Services GmbH  
**Global Support Centre**  
 P. O. Box 1252  
 D-82231 Wessling  
 E-Mail: gsc.op@328.eu  
 Telefax: +49 8153 88111 6565

From Company: \_\_\_\_\_

\_\_\_\_\_

Doc. No.	Rev.	Title
ASB-328J-25-019	2	Equipment/Furnishings - Cockpit Seats - Jammed AMSAFE Restraint System

Aircraft Serial Number: \_\_\_\_\_

Operator: \_\_\_\_\_

Total Flight Hours: \_\_\_\_\_ Total Landings: \_\_\_\_\_

Date of Compliance: \_\_\_\_\_

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_  
Date

\_\_\_\_\_  
Authorized Signature