



Revision Transmittal Sheet

This sheet transmits Revision 2 of Alert Service Bulletin ASB-328-25-040 titled:
Equipment/Furnishings - Cockpit Seats - Jammed AMSAFE Restraint System.

This is a complete revision. This has been reprinted in its entirety. All previous editions must be destroyed.

Reason for Revision:

On May, 24th 2017 EASA issued a revision of SIB 2016-16 following new in-service events reported on seat belt buckles outside the initial batch, forcing to extend the range of impacted seat belt buckles.

Page 1: updated section 'Reason'

Page 2: updated section 'References'

NOTE: The changes are marked with revision bars at the outside margin.

This Revision Transmittal Sheet is part of ASB-328-25-040 Revision 2 .

Model: Dornier 328-100

No.: ASB-328-25-040

Date of Issue: May 24, 2017

Page 1 of 1



ASB-328-25-040

Title: Equipment/Furnishings - Cockpit Seats - Jammed AMSAFE Restraint System

1 PLANNING INFORMATION

Effectivity

Dornier 328-100
Type Certificate Data Sheet EASA.A.096
Serial No.: All

Reason

EASA Safety Information Bulletin SIB 2016-16: AMSAFE Restraint Systems – Jammed Cockpit Seat Belt Buckles

Description

Reports were received by EASA of occurrences where pilots were unable to release their seat belts buckles. Affected AMSAFE Rotary Buckles are installed on IPECO pilot and co-pilot seat belt restraint systems P/N 1180002-()-() as installed on Dornier 328-100 aircraft.

Approval

The technical content of this Alert Service Bulletin is approved under the authority of EASA approved design organization 328 Design GmbH (EASA.21J.438).



© 328 Support Services GmbH 2006-2017. All Rights reserved.
This document is property of 328 Support Services GmbH and is supplied on the condition that it is treated as confidential. No use or reproduction may be made thereof other than that expressly authorized. The information provided by this ASB has been prepared for a specific Serial Number(s) aircraft, component, component part number or specific problem on the basis of the information supplied to 328 Support Services GmbH. The information provided by 328 Support Services GmbH is not to be used for any other specific serial Number(s) aircraft, component, component part number or any other purpose than for that which it was supplied without the written approval of 328 Support Services GmbH.
Any information contained in this ASB are Technical Documents and Data as defined in the Technical Data Agreement which 328 Support Services GmbH has separately concluded with the Customer. The Technical Data Agreement, especially the confidentiality obligations contained therein applies to any information provided by 328 Support Services GmbH in the course of the fulfilment of the ASB.

328 Support Services GmbH is the TC-Holder of Dornier 328-100 and 328-300 and authorised to provide necessary approved data. Any Dornier 328 approved data will be established and verified by 328 Design GmbH as authorised and responsible Dornier 328 Design Organisation per EASA approval EASA 21J.438. For details in this matter please contact 328 Support Services GmbH or EASA.

It is the operator's responsibility to comply with the relevant aviation regulations of the country in which the aircraft is registered.

Compliance

Highly recommended

Manpower

As required

Material

Refer to AMSAFE ASB 1150004-25-A01

Special Tools

Refer to AMSAFE ASB 1150004-25-A01

Weight and Balance

Not affected

Electrical Load Data

Not affected

References

EASA Safety Information Bulletin SIB 2016-16
or later revisions of the document approved by EASA

AMSAFE ASB 1150004-25-A01

IPECO SB 063-25-11

or later revisions of the above listed documents

Other Publications Affected

Not affected

Reporting

Compliance with this Alert Service Bulletin must be reported to 328 Support Services GmbH Global Support Centre with the Compliance Report for Configuration Control.



2. ACCOMPLISHMENT INSTRUCTIONS

- 1.) Do the following Service Bulletin:
 - a) AMSAFE ASB 1150004-25-A01.



**Dornier 328
Compliance Report**

328 Support Services GmbH

Customer Support • Global Support Centre
P. O. Box 1252 Phone: +49 8153 88111 6666
D-82231 Wessling Telefax: +49 8153 88111 6565
Germany E-Mail: gsc.op@328.eu



Please complete this compliance form for each aircraft only when it is applicable, and mail, e-mail, or fax to:

328 Support Services GmbH
Global Support Centre
P. O. Box 1252
D-82231 Wessling
E-Mail: gsc.op@328.eu
Telefax: +49 8153 88111 6565

From Company: _____

Doc. No.	Rev.	Title
ASB-328-25-040	2	Equipment/Furnishings - Cockpit Seats - Jammed AMSAFE Restraint System

Aircraft Serial Number: _____

Operator: _____

Total Flight Hours: _____ Total Landings: _____

Date of Compliance: _____

Comments: _____

Date

Authorized Signature